

Lecture 13, Feb 10, 2022

Imperfections

- There is no such thing as a perfect crystal – imperfections always exist
 - Certain types of defects are at equilibrium
 - Vacancies (missing atoms) create imperfections
 - The concentration of such defects affect how the material behaves
- Types of imperfections:
 - Point defects: Vacancies (missing atoms); interstitial/substitutional atoms (atoms that are on the wrong site)
 - * Interstitial atoms are extra atoms between atomic sites, distorting planes by pushing the atoms apart
 - * Self-interstitial is an interstitial atom that's the same atom as the crystal
 - * Vacancies also distort the plane structure as the atomic forces pull the surrounding atoms in
 - This is called a *strain* and has stored elastic energy
 - Line defects: Dislocations
 - Areal defects: Grain boundaries

Point Defects

- $\frac{N_v}{N} = e^{\frac{-Q_v}{kT}}$
 - N_v is the number of defects and N the number of defect sites
 - Q_v is the activation energy, k is the Boltzmann constant and T the temperature
 - Higher temperature allows atoms to overcome activation energy
 - Each lattice site is a potential vacancy site
- Activation energy can be measured through experiments using the defect concentration
- Vacancies cause “islands” to form on the surface
- When an impurity is added to a host there are 2 outcomes (this happens when the two substances don't naturally bond but are compatible):
 - Solid solution (random distribution of point defects)
 - * Substitutional solid (impurity in places where the host atoms were) or interstitial solid (impurity in between host atoms)
 - Solid solution plus particles of a second phase (usually for a larger amount of impurities when we go past the solubility)
 - * The impurity atoms and host atoms form a second phase with often different structure and composition
- Conditions for substitutional solid solution: Hume-Rothery rules
 1. $\Delta r < 15\%$ (atomic radii similar) (empirical)
 2. Proximity in the periodic table (similar electronegativity)
 3. Same crystal structure for pure metals
 4. Valency: Metal will have a greater tendency to dissolve a metal of higher valency than one of lower valency
- Quantifying composition: Weight percent $C_1 = \frac{m_1}{m_1 + m_2}$ or atomic percent $C_1 = \frac{n_{m1}}{n_{m1} + n_{m2}}$

Line Defects

- Dislocations are line defects
- Crystal planes slip when the material is placed under stress, e.g. zinc (HCP) under tensile elongation causes the diagonal planes to slip so the material can elongate (slip steps)
- Dislocations produce permanent (plastic) deformations
- Linear defects: 1D defects around which atoms are misaligned; 2 types:
 - Edge dislocation: Extra half-plane of atoms inserted into the structure
 - * *Burgers vector* b perpendicular to the dislocation line

- * The extra plane of atoms squeezed in deforms the crystal and pushes planes apart to make room
- Screw dislocation: Half-planes shear due to twisting
 - * Burgers vector is in the direction of the shear
- The two types of dislocations can be mixed
- Dislocations can be seen with an electron microscope as scattering changes due to the imperfections
- Edge dislocations can move along the Burgers vector by only breaking one bond at a time